



### Scope / explanations:

- Compressed air supply: 6 bar
- "0" position swivel arm: Standard (see illustration)
- Mounting position: Vertical (see illustration)
- All time data: Max. values of the needed process time to open or to close
- Load state [%]: Utilisation of the max. allowable torque on pivot pin due to load

