


Time need to open / to close

Sizes: 80 – 160

KS series



Scope / explanations:

Compressed air supply: 6 bar

"0" position swivel arm: Standard (see illustration)

Mounting position: Vertical (see illustration)

All time data: Max. values of the needed process time to open or to close

Load state [%]: Utilisation of the max. allowable torque on pivot pin due to load

