
Single parts for manual operation



Ordering example complete clamp:

APH 50 Z T12

APH: Type
50: Size
Z: Hand lever

Z RG = hand lever and retaining clip (closed position)

T12: Sensing system

Ordering example hand lever:

ZA 50

ZA: Hand lever complete consisting of: hand lever, ball and flange for clamp arm

50: Size ALPHA clamp

Ordering example retaining clip (closed position):

RGA 50

RGA: Retaining clip, (closed position)

50: Size ALPHA clamp

The hand lever is delivered unmounted for on-site mounting.

For further technical information see data sheet "APH...".

For further clamp arm versions see data sheet "Clamp arms - jaws for ALPHA-clamps".

Medium: Air, max. 6 bar, operation permitted with oil-free air. * Tolerance for dowel holes $\pm\,0.02$, for threaded holes $\pm\,0.1$.

