



Spare Parts List

MK 60 UZ

Spare Parts


06/01

Pos.	Part-No.	Quantity	Description	Type	Flag ¹
1	204027	1.00	housing	K 60 UZ	
2	203595	1.00	fork shaped piece complete	K 60 UZ	
3	202690	1.00	bolt	PKS 50 UZ	R
4	205349	2.00	roller	PKS 50 SHZ	R
5	205375	1.00	strap	PKS 50 UZ	R
6	202691	3.00	bolt	PKS 50 UZ	R
7	206443	1.00	fork shaped piece	PKS 50 UZ	
8	202607	2.00	bolt	PKS 50 U	R
9	203171	4.00	distance piece	PKS 50 UZ	
10	205376	1.00	strap	PKS 50 UZ	
11		1.00	clamping hook	depending on version	
12	202211	2.00	cover plate	PKS 32 U	
13	202856	8.00	bush	K 60 UZ	R
15	212973	1.00	Push-Pull clamp	HP 1200	
16	206111	1.00	receiver complete for Pos. 15	MK 60 UZ	
33	200124	4.00	slotted cheese head screw	M 4 x 6 DIN 84	
37	200611	4.00	set screw	M 4 x 5 DIN 915	R
38	201294	10.00	circlips for shafts	A12 x 1,00 DIN 471	R
39	201581	2.00	bush	12/14 x 10 DIN 17662	R
40	200052	2.00	hexagon screw	M 6 x 25 DIN 933	
41	200703	2.00	hexagon nut	M 6 DIN 934	
42	200051	4.00	hexagon screw	M 6 x 20 DIN 933	
43	200976	4.00	securing spring washer	S 6	
44	200229	4.00	hexagon socket head cap screw	M 8 x 50 DIN 912	
45	200755	4.00	washer	A 8,4 DIN 125	
46	200705	4.00	hexagon nut	M 8 DIN 934	
47	200601	1.00	set screw	M 10 x 60 DIN 914	
48	200706	2.00	hexagon nut	M 10 DIN 934	
68		1.00	combination of plate and centering mandrel welded or screwed		
68.1		1.00	plate for centering mandrel	depending on version	
68.2		1.00	centering mandrel	depending on version	
70	204266	1.00	housing lid	K 60 UZ	
71	200413	4.00	hexagon socket head cap screw	M 5 x 12 DIN 6912	
72	201257	2.00	parallel pin	D 5 m6 x 16 DIN 7979	
73	200975	4.00	securing spring washer	S 5	

spare parts / accessories

Pos.	Part-No.	Quantity	Description	Type	
	234583	1.00	repair kit	MK 60 UZ	
	1377062000	1.00	limit switch set complete	K 60 UZ T12	

¹ R = included with repair kit



TÜNKERS®
SPANNSYSTEME

TÜNKERS® Maschinenbau GmbH
Am Rosenkothen 8 • D-40880 Ratingen
Postfach 10 17 16 • D-40837 Ratingen
Tel. 02102 4517-0 • Fax 02102 445808
Internet www.tuenkers.de